


# Re-entry trajectory for RDM Test Case #5

Covered period: last 45 min




30-NOV-2018 13:48:57.9

# Re-entry trajectory for RDM Test Case #5




Enlargement of the impact area



# Re-entry trajectory for RDM Test Case #5

Covered period: +/- 90 min around break-up point (BU)



30-NOV-2018 13:48:57.9